



M/S PANKAJ M. AKHANDE

(Fire Protection & Fighting Systems)

Office/Works :Plot No 63,Shashikant Society,Parroti Nagar Nagpur-13 E-Mail: pankajmahadeora@gmail.com
Contact:7385170750

REF NO.PMA/AAH/25-26/FB-13

FORM - B

{(see section 3 (3) and rule 4 (2))}

Six monthly certificate to be given in every January and July by the owner or the
Occupier for compliance of the Fire Prevention and Life Safety Measures

CERTIFICATE

Certified that I / We have carried out inspection of the Fire Prevention and
Life Safety Measures installed in the following building or premises. Namely:-

MS.ANTYODAYA AYURVEDIC HOSPITAL, DEVGRAM TAH-NARKHED, NAGPUR 441301

I / We further certify that these installations in the above mentioned
Buildings are maintained in good repair and efficient conditions during the period
Of 1st of Jan 2025 to 30th of Jun 2025, as required under the provisions of the
Maharashtra Fire Prevention and Life Safety Measures Act, 2006 (Mah-III of 2007).

The details of the inspection of installations carried out by me / us are mentioned in
the report appended herewith in Annexure.

Place: NAGPUR

Date: Signature and address of the

PANKAJ
MAHADEORA
O AKHANDE
Licensed Agency

Digitally signed by
PANKAJ MAHADEORA
AKHANDE
Date: 2025.05.24
13:19:14 +05'30

Principal
Antyodaya Institute of Ayurvedic Medical
Science, Research Center and Hospital, Gavgam

License No: MFS/LA/RF-250

MFS/LA/RD-230

MFS/LA/RP-70

M/S PANKAJ MAHADEORA

(Fire Protection & Fire Fighting Systems)

Office/Works :Plot No 63,Shashikant Society,Pallon, Nagar, Nagpur-481114
 Contact: 7183120750

ANNEXURE FOR EXECUTION/ MAINTENANCE

Name of the Building	ANTYODAYA AYURVEDIC HOSPITAL, DEVGRAM TAH-NARKHE, NAGPUR 441301				
Classification of Building	HOSPITAL BUILDING	Height of Building:	11.23	MTR	
Main Pump	NA	NOS	LPM		
Diesel Pump	NA	NOS	LPM		
Jockey pump	NA	LPM	Terrace Pump	01	7.5 HP
Pump Electrical Panel	1	NOS	Fire Alarm Panel	01	Nos
Wet Rise/ Down Comer	100	MM	Number Of Wings	NA	Nos
Fire Service Inlet	01	NOS	Court Yard Hydrant		
Sr. No.	List Of Equipment	Ground Floor	1 st Floor	Total	Status
1	Hydrant Valve Staircase	05Nos	05Nos	10 Nos	Working & Healthy Condition
2	Hose Reel	05Nos	05Nos	10 Nos	Working & Healthy Condition
3	Hose Box	05Nos	05Nos	10 Nos	Working & Healthy Condition
4	Hose pipe 30MTR	05Nos	05Nos	10 Nos	Working & Healthy Condition
5	Branch Pipe	05Nos	05Nos	10 Nos	Working & Healthy Condition
6	Sprinkler Head	N.A	N.A	N.A	Working & Healthy Condition
7	Fire Extinguisher -ABC KG6	10 Nos	10Nos	10Nos	Working & Healthy Condition
8	Fire Extinguisher - CO2	N.A	N.A	N.A	Working & Healthy Condition
9	Manual Call Point	05Nos	05Nos	10Nos	Working & Healthy Condition
10	Hooter	05Nos	05Nos	10Nos	Working & Healthy Condition
11	Heat Detectors	N.A	N.A	N.A	Working & Healthy Condition
12	Smoke Detectors	N.A	N.A	N.A	Working & Healthy Condition

Principal
 Antyodaya Institute of Ayurvedic Medical
 Science, Research Center and Hospital, Devgram

**PANKAJ
 MAHADEORA
 O AKI-ANDE**

Digitally signed by
 PANKAJ
 MAHADEORA
 AKHANDE
 Date: 2025.05.24
 18:19:39 +05'30'